




roughly coursed rubble walling.

Above: section AA  
Hood moulding.



S.W. QUOIN L&S WORK,  
shown in relative  
(actual) position to archway.

CHURCH of ST. ANDREW.  
BRIGSTOCK.  
ANGLO-SAXON ARCH,  
to tower/nave.