

Church of St. James, Selham, West Sussex.

1.

1. The church from the NW. Some evidence in the NW lower quoin of long-and-short work (the west wall rebuilt later).
2. Chancel arch from the nave.
3. Nave, and chancel beyond, the random rubble of the walling seen from the NW (that of the chancel partly coursed).
4. The N doorway to nave.
5. South capital, chancel arch, seen from the west (& see pic 7), scrolls and monsters.
6. North capital, chancel arch - both Saxon and Roman, the impost is a reused Roman fragment, obvious in its (truncated) classical section (see Taylor & Taylor).
7. South capital seen again here, strange in its 'tiered' top heavy effect, it is actually deeper in height than its sister (possibly reusing existing worked stones).

